



What's NEW in VERICUT Composites Simulation 9.6.2

IMPORTANT! – Licensing is NOT included with software shipments. See “To Get a License” below for details

December 17, 2025

Dear VERICUT® Composites Simulation User:

Thank you for your continued investment in VERICUT Composites Simulation (VCS), an important part of your NC programming and machining process!

VERICUT Composites Simulation 9.6.2 is packed with new features making it more powerful and easier to use. This letter describes important changes in VERICUT Composites Simulation 9.6.2. Please take a moment to review what's new and improved in this release.

Maintenance and Licensing Information

NOTE: This software requires VERICUT 9.6 licensing and Sentinel 9.8.1 License Server installation.

To Get a License – use the link below to submit a License Request:

http://www.cgtech.com/vericut_support/request-license/.

Licensing is sent via Email only.

VCS 9.6.2 runs on 64-bit Windows, and is supported on Windows 10 and 11 computers.

Software maintenance keeps you on the cutting edge - CGTech provides update software to customers with current software maintenance. Your continued maintenance ensures that you have the most advanced verification technology available. If your maintenance has expired, please contact your CGTech representative (<http://www.cgtech.com/about/contact-us/>).

Sincerely,
Olivier Munaux
CGTech VERICUT Composites Product Manager

VCS 9.6.2

Enhancements and Changes in V9.6.2

Enhanced the macro MountToCompName if called before robot initialization, no error message is returned.

VCS 9.6.1.1

Enhancements and Changes in V9.6.1.1

Enhanced cancel handling for better responsiveness in the GUI.

VCS 9.6.1

Enhancements and Changes in V9.6.1

New Stop At: Sync option has been added to simulation playback.

Problems Resolved in V9.6.1

Issues of unexpected termination and slowdown have been corrected.

An issue of false collision reports generating in certain circumstances has been corrected.

An issue of View Cube not working properly has been resolved.

VCS 9.6.0.1

Problems Resolved in V9.6.0.1

An issue where poor tape projection caused an incorrect collision detection has been resolved.

VCS 9.6

Enhancements and Changes in V9.6

Updates to Tape Head help document section have been made.

Updates to the Tape Manager help document section have been made to include Bulk Factor.

Updates to the Information help document section has been made.

Updates to the *Peel off layer* help document section has been made.

Several updates to VCS Samples have been made.

Problems Resolved in V9.6

An issue where poor tape projection caused an incorrect collision detection has been resolved.

An issue with the formatting of the Tape Laying Sequence Statistics information when printing has been resolved.

Several issues in VCS Report Generator have been resolved.

An issue where poor tape projection caused an incorrect collision detection has been resolved.